
DRAFTSMAN



Prof. Herly door



2/3




FIG. 2




FIG. 3

DRAFTSMAN





3/3

	EFFECT OF INCREASE ON			
INCREASE IN:	n	k	t	r
TEMPERATURE	1	1	1	1
PRESSURE	1	ļ	$\downarrow$	<b>↓</b>
POWER	$\downarrow$	1	<b>†</b>	<b>↓</b>
SPACING	<b>↓</b>	$\downarrow$	ţ	<b>↓</b>
SiH <sub>4</sub>	<b>†</b>	<b>†</b>	<b>†</b>	<b>†</b>
N <sub>2</sub> 0	<b>↓</b>	<b>↓</b>	<b>†</b>	ţ
NH <sub>3</sub>	<b>†</b>	<b>↓</b>	<b>†</b>	. ↓
N <sub>2</sub>	1	$\downarrow$	<b>†</b>	<b>↓</b>
Не	<b>†</b>	<b>†</b>	$\downarrow$	<b>†</b>
TOTAL GAS FLOW	<b>†</b>	<b>↑</b>	<b>↑</b>	<b>†</b>

FIG. 4